



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Penn Center Channel #1

Activity: Routine/Preventive Maintenance

Duration: 11/27/17

Narrative Description of Project:

Project improved 2,040 L.F. of drainage system. Cleaned out 2,040 L.F. of channel.

2018-544 / Penn Center Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
CCO / Channel - cleaned out	40.0	\$891.00	\$182.49	\$35.39	\$0.00	\$530.90	\$1,639.78
2018-544 / Penn Center Channel #1 Sub Total	40.5	\$901.90	\$182.49	\$35.39	\$0.00	\$530.90	\$1,650.68
Grand Total	40.5	\$901.90	\$182.49	\$35.39	\$0.00	\$530.90	\$1,650.68

Before



During



After





Project: Penn Center Channel #1

Activity: Routine/ Preventive Maintenance

Project #: 2018-544

Township/SW Dist: St. Helena Island/8

Completed: November 2017

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 420 feet

Prepared By: BC Stormwater Management Utility

Date Print: 03/08/18

File: C:\project summaries map\Penn Center Channe #1_2018-544