



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Glaze Drive

**Activity:** Routine/Preventive Maintenance

**Duration:** 05/22/18-07/09/18

**Narrative Description of Project:**

Project improved 1,740 L.F. of drainage system. Cleaned out 1,740 L.F. of roadside ditch. Jetted (24) driveway pipes.

**2018-610 / Glaze Drive**

	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
DPJT / Driveway Pipe - Jetted	28.0	\$623.84	\$536.48	\$125.15	\$0.00	\$401.52	\$1,686.99
HAUL / Hauling	32.0	\$645.64	\$339.42	\$89.31	\$0.00	\$26.63	\$1,101.00
RSDCL / Roadside Ditch - Cleanout	70.0	\$1,507.50	\$399.10	\$111.78	\$0.00	\$716.10	\$2,734.48
UTLOC / Utility locates	1.5	\$37.05	\$0.00	\$0.00	\$0.00	\$19.85	\$56.90
2018-610 / Glaze Drive Sub Total	132.5	\$2,835.82	\$1,275.00	\$326.24	\$0.00	\$1,164.10	\$5,601.15
<b>Grand Total</b>	<b>132.5</b>	<b>\$2,835.82</b>	<b>\$1,275.00</b>	<b>\$326.24</b>	<b>\$0.00</b>	<b>\$1,164.10</b>	<b>\$5,601.15</b>

**Before**



**During**



**After**







Project: Glaze Drive

Activity: Routine/ Preventive Maintenance

Project #: 2018-610

Township/SW Dist: Port Royal Island/6

Completed: July 2018

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 250 feet