



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** McRiley Complex

**Activity:** Routine/Preventive Maintenance

**Duration:** 03/05/18

**Narrative Description of Project:**

Repaired sinkhole.

**2018-582 / MC Riley Complex**

	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
SR / Sinkhole repair	16.0	\$376.94	\$36.00	\$83.64	\$0.00	\$246.96	\$743.54
2018-582 / MC Riley Complex Sub Total	16.5	\$387.84	\$36.00	\$83.64	\$0.00	\$246.96	\$754.43
Grand Total	<b>16.5</b>	<b>\$387.84</b>	<b>\$36.00</b>	<b>\$83.64</b>	<b>\$0.00</b>	<b>\$246.96</b>	<b>\$754.43</b>

**(Pictures Not Available)**





Project: MC Riley Complex

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2018-582

Township/SW Dist:  
Bluffton/4

Completed:  
March 2018

### Legend

#### Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 50 100 200 300 400  
Feet

1 inch = 210 feet

Prepared By: BC Stormwater Management Utility  
Date Print: 08/13/18  
File: C:\project summaries map\MC Riley Complex\_2018-582