

## Beaufort County Public Works Stormwater Infrastructure

**Project Summary** 

Project Summary: Scott Hill Road Activity: Routine/Preventive Maintenance

**Duration:** 02/06/18-02/12/18

## **Narrative Description of Project:**

Project improved 780 L.F. of drainage system. Cleaned out 780 L.F. of roadside ditch.

| 2018-572 / Scott Hill Road           | Labor | Labor    | Equipment | Material | Contractor | Indirect | Total      |
|--------------------------------------|-------|----------|-----------|----------|------------|----------|------------|
|                                      | Hours | Cost     | Cost      | Cost     | Cost       | Labor    | Cost       |
| AUDIT / Audit Project                | 0.5   | \$10.90  | \$0.00    | \$0.00   | \$0.00     | \$0.00   | \$10.90    |
| HAUL / Hauling                       | 15.0  | \$314.30 | \$141.30  | \$66.64  | \$0.00     | \$0.00   | \$522.24   |
| RSDCL / Roadside Ditch - Cleanout    | 15.0  | \$303.90 | \$67.54   | \$21.42  | \$0.00     | \$188.25 | \$581.11   |
| 2018-572 / Scott Hill Road Sub Total | 30.5  | \$629.10 | \$208.84  | \$88.06  | \$0.00     | \$188.25 | \$1,114.24 |
| Grand Total                          | 30.5  | \$629.10 | \$208.84  | \$88.06  | \$0.00     | \$188.25 | \$1,114.24 |

## **Before**



During



After

