



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Airport Circle

Activity: Routine/Preventive Maintenance

Duration: 04/05/18

Narrative Description of Project:

Project improved 290 L.F. of drainage system. Cleaned out 290 L.F. of roadside ditch.

2018-589 / Airport Circle	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
HAUL / Hauling	11.0	\$257.12	\$103.62	\$72.62	\$0.00	\$168.87	\$602.23
RSDCL / Roadside Ditch - Cleanout	21.0	\$433.86	\$112.77	\$15.54	\$0.00	\$270.69	\$832.86
2018-589 / Airport Circle Sub Total	32.5	\$701.88	\$216.39	\$88.16	\$0.00	\$439.56	\$1,445.98
Grand Total	32.5	\$701.88	\$216.39	\$88.16	\$0.00	\$439.56	\$1,445.98

Before



During



After





Project: Airport Circle

Activity: Routine/
Preventive
Maintenance














Project #:
2018-589

Township/SW Dist:
Ladys Island/7

Completed:
April 2018

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 330 feet