



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: George Williams Lane

Activity: Routine/Preventive Maintenance

Duration: 02/06/18-02/14/18

Narrative Description of Project:

Installed (1) driveway pipe.

2018-569 / George Williams Lane	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
DPINS / Driveway Pipe - Installed	18.0	\$400.98	\$118.12	\$482.59	\$0.00	\$257.58	\$1259.27
HAUL / Hauling	12.0	\$249.30	\$113.04	\$486.16	\$0.00	\$86.52	\$935.02
UTLOC / Utility locates	1.5	\$37.05	\$6.03	\$12.18	\$0.00	\$19.85	\$75.11
2018-569 / George Williams Lane Sub Total	32.0	\$698.23	\$237.19	\$980.93	\$0.00	\$363.94	\$2,280.29
Grand Total	32.0	\$698.23	\$237.19	\$980.93	\$0.00	\$363.94	\$2,280.29

Before



During



After





Project: George Williams Lane

Activity: Routine/
Preventive
Maintenance














Project #:
2018-569

Township/SW Dist:
Sheldon/5

Completed:
February 2018

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 40 80 160 240 320
Feet

1 inch = 170 feet

Prepared By: BC Stormwater Management Utility
Date Print: 06/21/18
File: C:\project summaries map\George Williams Lane_2018-569