

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Port Royal Island Valley Drains

Activity: Routine/Preventive Maintenance


Duration: 11/19/18-11/29/18


Narrative Description of Project:


Project improved 10,102 L.F. of drainage system. Cleaned out 10,102 L.F. of valley drains. This project consisted of the following areas: Mulrain Road (1,928 L.F.), Smalls Drive (1,470 L.F.), Poppy Hill Road (4,254 L.F.), Donaldson Camp Road (2,450 L.F.)

2019-314 / Port Royal Island Valley Drains	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
COVD / Cleaned Out Valley Drains	136.0	\$2,949.21	\$508.91	\$202.65	\$0.00	\$1,460.73	\$5,121.50
HAUL / Hauling	38.0	\$826.51	\$538.08	\$128.70	\$0.00	\$331.66	\$1,824.95
2019-314 / Port Royal Island Valley Drains Sub Total	175.0	\$3,797.51	\$1,046.99	\$331.35	\$0.00	\$1,792.39	\$6,968.24
Grand Total	175.0	\$3,797.51	\$1,046.99	\$331.35	\$0.00	\$1,792.39	\$6,968.24

(No Pictures Available)









Project: Port Royal Island Valley **Drains- Donaldson** Camp Road Map #4

Activity: Routine/ Preventive Maintenance

Project #: 2019-314

Township/SW Dist: Port Royal Island/6

Completed: November 2018

Legend

Drainage Type

- Access Pipe
 - Bleeder Pipe
- Channel Pipe
 - Channel
 - Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe