



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Marsh Drive

**Activity:** Routine/Preventive Maintenance

**Duration:** 06/11/19-06/26/19

**Narrative Description of Project:**

Project improved 280 L.F. of drainage system. Bush hogged 150 L.F. of channel. Cleaned out 150 L.F. of channel. Jetted 130 L.F. of channel pipe.

**2019-573 / Marsh Drive**

	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	2.0	\$43.58	\$0.00	\$0.00	\$0.00	\$0.00	\$43.58
CBH / Channel- bushhogged	2.0	\$49.40	\$50.44	\$0.00	\$0.00	\$32.94	\$132.78
CCO / Channel - cleaned out	15.0	\$431.40	\$39.47	\$21.16	\$0.00	\$133.35	\$625.38
CPJ / Channel Pipe - Jetted	4.0	\$88.38	\$76.64	\$40.34	\$0.00	\$32.94	\$238.30
HAUL / Hauling	7.0	\$157.33	\$140.08	\$69.02	\$0.00	\$72.10	\$438.53
UTLOC / Utility locates	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
2019-573 / Marsh Drive Sub Total	30.5	\$780.99	\$306.63	\$130.52	\$0.00	\$271.33	\$1,489.47
<b>Grand Total</b>	<b>30.5</b>	<b>\$780.99</b>	<b>\$306.63</b>	<b>\$130.52</b>	<b>\$0.00</b>	<b>\$271.33</b>	<b>\$1,489.47</b>

**Before**



**During**

**(No Pictures Available)**

**After**



Project: Marsh Drive

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2019-573

Township/SW Dist:  
Lady's Island/7

Completed:  
June 2019



Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 250 feet