



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Sea Island Parkway

Activity: Routine/Preventive Maintenance

Duration: 03/26/19-05/23/19

Narrative Description of Project:

Project improved 1,458 L.F. of drainage system. Grubbed and cleared 120 L.F. of lateral ditch and 1,338 L.F. of workshelf. Cleaned out 120 L.F. of lateral ditch and 1,338 L.F. of channel. Installed (2) access pipes. Handseeded for erosion control.

2019-559 / Sea Island Parkway	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
APINS / Access pipe - installed	20.0	\$652.20	\$75.26	\$171.00	\$0.00	\$134.40	\$1,032.86
AUDIT / Audit Project	2.0	\$43.58	\$0.00	\$0.00	\$0.00	\$0.00	\$43.58
CCO / Channel - cleaned out	54.0	\$1,629.74	\$322.01	\$108.17	\$0.00	\$295.68	\$2,355.60
DEBREM / Debris Removal - Jobsite	30.0	\$862.80	\$150.34	\$32.67	\$0.00	\$266.70	\$1,312.51
HAND / HANDSEDED	15.0	\$431.40	\$18.00	\$217.97	\$0.00	\$133.35	\$800.72
HAUL / Hauling	40.5	\$898.97	\$446.64	\$381.45	\$0.00	\$300.85	\$2,027.91
RMTRW / Remove trees - Workshelf	10.0	\$210.60	\$246.68	\$95.18	\$0.00	\$132.30	\$684.76
WSDR / Workshelf - Dressed	104.0	\$2,888.35	\$962.89	\$346.92	\$0.00	\$892.71	\$5,090.87
WSGRB / Workshelf - Grubbed	288.0	\$8,267.18	\$2,233.02	\$393.78	\$0.00	\$2,428.02	\$13,322.00
2019-559 / Sea Island Parkway Sub Total	563.5	\$15,884.82	\$4,454.84	\$1,747.14	\$0.00	\$4,584.01	\$26,670.81
Grand Total	563.5	\$15,884.82	\$4,454.84	\$1,747.14	\$0.00	\$4,584.01	\$26,670.81

Before


During

After

(No Picture Available)

(No Picture Available)





Project: Sea Island Parkway Map #1

Activity: Routine/ Preventive Maintenance

Project #: 2019-559

Township/SW Dist: St Helena Island/8

Completed: May 2019

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 50 100 200 300 400 Feet

1 inch = 210 feet

Prepared By: BC Stormwater Management Utility

Date Print:06/20/19

File:C:\project summaries map\ Sea Island Parkway Map #1_2019-559


Project: Sea
Island Parkway
Map #2

Activity: Routine/
Preventive
Maintenance

Project #:
2019-559

Township/SW Dist:
St Helena Island/8

Completed:
May 2019



Grubbed and cleared 120 LF
of lateral ditch. Cleaned out
120 LF of lateral ditch.

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe



1 inch = 130 feet

Prepared By: BC Stormwater Management Utility
Date Print:06/20/19
File:C:\project summaries map\ Sea Island Parkway Map #2_2019-559