

## **Beaufort County Public Works** Stormwater Infrastructure

**Project Summary** 

**Project Summary:** Sheldon Vacuum Truck

George Williams Lane, Paige Point Bluff, Jasmine Hall Road, Big Estate Road,

Johnson Road and Witsell Road

**Activity:** Routine/Preventive Maintenance

**Duration:** 01/03/19-04/03/19

## **Narrative Description of Project:**

Removed blockages from flowline. Jetted (1) access pipe, (9) driveway pipes and (3) crossline pipes.


| 2019-308A / Sheldon Vacuum Truck           | Labor  | Labor      | <b>Equipment</b> | Material | Contractor | Overhead | Total      |
|--|--------|------------|------------------|----------|------------|----------|------------|
|  | Hours  | Cost       | Cost             | Cost     | Cost       | Cost     | Cost       |
| AUDIT / Audit Project                      | 1.5    | \$32.69    | \$0.00           | \$0.00   | \$0.00     | \$0.00   | \$32.69    |
| CLPJT / Crossline Pipe - Jetted            | 36.0   | \$802.08   | \$689.76         | \$107.86 | \$0.00     | \$516.24 | \$2115.94  |
| DPJT / Driveway Pipe - Jetted              | 18.0   | \$401.04   | \$344.88         | \$84.06  | \$0.00     | \$258.12 | \$1,088.10 |
| RB / Remove blockage from flowline         | 4.0    | \$89.12    | \$76.64          | \$23.30  | \$0.00     | \$57.36  | \$246.42   |
| STBY / Stand By                            | 4.0    | \$89.12    | \$17.36          | \$0.00   | \$0.00     | \$57.36  | \$163.84   |
| 2019-308A / Sheldon Vacuum Truck Sub Total | 63.5   | \$1,414.05 | \$1,128.64       | \$215.22 | \$0.00     | \$889.08 | \$3,646.98 |
| Grand Total                                | 63.5   | \$1,414.05 | \$1128.64        | \$215.22 | \$0.00     | \$889.08 | \$3,646.98 |
| Refore                                     | Durina |            |                  |          |            | After    |            |


Before





(No Picture Available)
















Project: Sheldon Vacuum Truck-Johnson Road Map #6

Activity: Routine/ Preventive Maintenance

Project #: 2019-308A

Township/SW Dist: Sheldon/5

Completed: April 2019

## Legend

## **Drainage Type**

- Access Pipe
- Bleeder Pipe
- Channel Pipe
  - Channel
  - Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
  - River
- Road Pipe
- Roadside
- Roadside Pipe

Date Print:07/24/19

Feet

File:C:\project summaries map/Sheldon Vacuum Truck- Johnson Road Map #6\_2019-308A

