



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Sheldon Tree Removal- Mitchell Road

**Activity:** Routine/Preventive Maintenance

**Duration:** 07/31/18-04/23/19

**Narrative Description of Project:**

Removed fallen trees from workshelf and blockage from flowline.

<b>2019-510 / Sheldon Tree Removal</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
HAUL / Hauling	6.0	\$133.62	\$84.96	\$125.78	\$0.00	\$86.52	\$430.88
RMTRW / Remove trees - Workshelf	4.0	\$86.11	\$7.53	\$9.32	\$0.00	\$42.93	\$145.89
2019-510 / Sheldon Tree Removal Sub Total	11.0	\$241.52	\$92.49	\$135.10	\$0.00	\$129.45	\$598.55
<b>Grand Total</b>	<b>11.0</b>	<b>\$241.52</b>	<b>\$92.49</b>	<b>\$135.10</b>	<b>\$0.00</b>	<b>\$129.45</b>	<b>\$598.55</b>

**(No Pictures Available)**



Project: Sheldon  
Tree Removal -  
Mitchell Road

Activity: Routine/  
Preventive  
Maintenance














Project #:  
2019-510

Township/SW Dist:  
Sheldon/5

Completed:  
April 2019

### Legend

#### Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 70 140 280 420 560  
Feet

1 inch = 290 feet

Prepared By: BC Stormwater Management Utility

Date Print: 010/29/19

File: C:\project summaries map\Sheldon Tree Removal - Mitchell Road\_2019-510