



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: David Green Road Channel #1

Activity: Routine/Preventive Maintenance

Duration: 05/30/18-05/31/18

Narrative Description of Project:

Project improved 3,190 L.F. of drainage system. Cleaned out 3,190 L.F. of channel.

2018-622 / David Green Road Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
CCO / Channel - cleaned out	60.0	\$1,256.80	\$357.85	\$82.28	\$0.00	\$643.20	\$2,340.13
HAUL / Hauling	10.0	\$222.70	\$94.20	\$94.38	\$0.00	\$144.20	\$555.48
2018-622 / David Green Road Channel #1 Sub Total	70.5	\$1,490.40	\$452.05	\$176.66	\$0.00	\$787.40	\$2,906.51
Grand Total	70.5	\$1,490.40	\$452.05	\$176.66	\$0.00	\$787.40	\$2,906.51

Before



During



After

(Picture Not Available)



Project: David
Green Road
Channel #1

Activity: Routine/
Preventive
Maintenance

Project #:
2018-622

Township/SW Dist:
St. Helena Island/8

Completed:
May 2018

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 120240 480 720 960
Feet

1 inch = 500 feet

Prepared By: BC Stormwater Management Utility

Date Print: 02/07/19

File: C:\project summaries map\David Green Road Channel #1_2018-622