



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Leg O Mutton Road

Activity: Routine/Preventive Maintenance

Duration: 04/11/18-06/14/18


Narrative Description of Project:

Project improved 453 L.F. of drainage system. Cleaned out 153 L.F. of roadside ditch. Jetted (4) crossline pipes and 300 L.F. of channel pipe.

2018-597 / Leg O Mutton Road

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CLPJT / Crossline Pipe - Jetted	105.0	\$2,339.35	\$274.60	\$290.85	\$0.00	\$1,260.20	\$4,165.00
HAUL / Hauling	5.0	\$111.35	\$47.10	\$37.65	\$0.00	\$72.10	\$268.20
RSDCL / Roadside Ditch - Cleanout	40.0	\$932.20	\$87.94	\$32.94	\$0.00	\$543.20	\$1,596.28
SG / Shoot Grade	6.0	\$133.66	\$7.20	\$0.00	\$0.00	\$85.86	\$226.72
UTLOC / Utility locates	0.5	\$12.35	\$0.00	\$0.00	\$0.00	\$6.62	\$18.97
2018-597 / Leg O Mutton Road Sub Total	157.5	\$3,550.70	\$416.84	\$361.44	\$0.00	\$1,967.98	\$6,296.96
Grand Total	157.5	\$3,550.70	\$416.84	\$361.44	\$0.00	\$1,967.98	\$6,296.96

Before




During



After

(Picture Not Available)



Project: Leg O Mutton Road

Activity: Routine/ Preventive Maintenance

Project #: 2018-597

Township/SW Dist: Hilton Head Island/ 3

Completed: June 2018

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 130 feet