



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Broad River Boulevard

Activity: Routine/Preventive Maintenance

Duration: 02/11/2019

Narrative Description of Project:

Project improved 300 L.F. of drainage system. Cleaned out 300 L.F. of channel.

2019-545 / Broad River Blvd	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CCO / Channel - cleaned out	20.0	\$481.80	\$138.72	\$45.44	\$0.00	\$276.50	\$942.46
HAUL / Hauling	10.0	\$222.70	\$141.60	\$44.80	\$0.00	\$144.20	\$553.30
2019-545 / Broad River Blvd Sub Total	31.0	\$726.29	\$280.32	\$90.24	\$0.00	\$420.70	\$1,517.55
Grand Total	31.0	\$726.29	\$280.32	\$90.24	\$0.00	\$420.70	\$1,517.55

(No Pictures Available)

Project: Broad River Boulevard

Activity: Routine/ Preventive Maintenance

Project #: 2019-545

Township/SW Dist: Port Royal Island/6

Completed: February 2019



Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 250 feet