



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Burton Wells Road and Middleton Recreation Drive

Activity: Routine/Preventive Maintenance

Duration: 08/22/18-09/10/18

Narrative Description of Project:

Project improved 510 L.F. of drainage system. Cleaned out 510 L.F. of roadside ditch.

2019-519 / Burton Wells Rd. & Middleton Recreation Dr.

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
HAUL / Hauling	9.0	\$198.03	\$127.44	\$22.86	\$0.00	\$57.68	\$406.01
RSDCL / Roadside Ditch - Cleanout	25.0	\$538.75	\$67.54	\$22.86	\$0.00	\$341.85	\$971.00
UTLOC / Utility locates	0.5	\$12.35	\$0.00	\$0.00	\$0.00	\$6.62	\$18.97
2019-519 / Burton Wells Rd. & Middleton Recreation Dr. Sub Total	35.5	\$770.92	\$194.98	\$45.72	\$0.00	\$406.14	\$1,417.76
Grand Total	35.5	\$770.92	\$194.98	\$45.72	\$0.00	\$406.14	\$1,417.76

Before



During



After



Project: Burton Wells Road and Middleton Recreation Drive

Activity: Routine/ Preventive Maintenance

Project #: 2019-519

Township/SW Dist: Port Royal Island/6

Completed: September 2018



Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 130 feet