



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Dan Drive

Activity: Routine/Preventive Maintenance

Duration: 08/21/18-11/21/18

Narrative Description of Project:

Project improved 559 L.F. of drainage system. Cleaned out 559 L.F. of channel. Jetted (1) access pipe, (1) driveway pipe and (1) crossline pipe.

2019-518 / Dan Drive

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CCO / Channel - cleaned out	15.0	\$461.70	\$76.46	\$47.40	\$0.00	\$139.30	\$724.86
DPJT / Driveway Pipe - Jetted	20.0	\$445.60	\$383.20	\$33.50	\$0.00	\$286.80	\$1,149.10
HAUL / Hauling	4.0	\$89.08	\$97.60	\$63.70	\$0.00	\$57.68	\$308.06
UTLOC / Utility locates	1.5	\$37.05	\$0.00	\$0.00	\$0.00	\$19.85	\$56.90
2019-518 / Dan Drive Sub Total	41.5	\$1,055.22	\$557.26	\$144.60	\$0.00	\$503.63	\$2,260.71
Grand Total	41.5	\$1,055.22	\$557.26	\$144.60	\$0.00	\$503.63	\$2,260.71

Before



During



After





Project: Dan Drive

Activity: Routine/
Preventive
Maintenance

Project #:
2019-518

Township/SW Dist:
Sheldon/5

Completed:
November 2018

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 83 feet