



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Fox Island Road

**Activity:** Routine/Preventive Maintenance

**Duration:** 10/15/18

**Narrative Description of Project:**

Project improved 4 L.F. of drainage system. Extended 4 L.F. of crossline pipe.

2019-526 / Fox Island Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CLPEX / Crossline Pipe - Extended	15.0	\$334.15	\$75.26	\$135.87	\$0.00	\$214.65	\$759.93
HAUL / Hauling	8.0	\$178.16	\$113.28	\$68.49	\$0.00	\$115.36	\$475.29
2019-526 / Fox Island Road Sub Total	24.0	\$534.10	\$188.54	\$204.36	\$0.00	\$330.01	\$1,257.01
<b>Grand Total</b>	<b>24.0</b>	<b>\$534.10</b>	<b>\$188.54</b>	<b>\$204.36</b>	<b>\$0.00</b>	<b>\$330.01</b>	<b>\$1,257.01</b>

**Before**



**During**



**After**







Project: Fox Island Road

Activity: Routine/  
Preventive  
Maintenance














Project #:  
2019-526

Township/SW Dist:  
Bluffton/4

Completed:  
October 2018

### Legend

#### Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 20 40 80 120 160  
Feet

1 inch = 83 feet

Prepared By: BC Stormwater Management Utility

Date Print: 04/16/19

File: C:\project summaries map\Fox Island Road\_2019-526