



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Half Moon Island Road

Activity: Routine/Preventive Maintenance

Duration: 07/25/18

Narrative Description of Project:

Repaired sinkhole.

2019-505 / Half Moon Island Road

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Cost	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
HAUL / Hauling	8.0	\$175.92	\$113.28	\$658.96	\$0.00	\$65.88	\$1,014.04
SD / Soft Digging	8.0	\$178.24	\$153.28	\$17.68	\$0.00	\$114.72	\$463.92
SR / Sinkhole repair	12.0	\$267.32	\$34.03	\$11.45	\$0.00	\$171.72	\$484.52
UTLOC / Utility locates	6.0	\$251.70	\$10.80	\$4.22	\$0.00	\$89.73	\$356.45
2019-505 / Half Moon Island Road Sub Total	35.0	\$894.97	\$311.39	\$692.30	\$0.00	\$442.05	\$2,340.71
Grand Total	35.0	\$894.97	\$311.39	\$692.30	\$0.00	\$442.05	\$2,340.71

Before



During

(No Picture Available)

After

(No Picture Available)



Project: Halfmoon Island Road

Activity: Routine/ Preventive Maintenance














Project #: 2019-505

Township/SW Dist: Sheldon/5

Completed: July 2018

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 80 160 320 480 640 Feet

1 inch = 330 feet

Prepared By: BC Stormwater Management Utility

Date Print: 03/29/19

File: C:\project summaries map\Halfmoon Island Road_2019-505