



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Hunters Grove Road

Activity: Routine/Preventive Maintenance


Duration: 03/11/19-03/13/19

Narrative Description of Project:

Project improved 400 L.F. of drainage system. Grubbed and cleared 25 L.F. of workshelf. Cleaned out 400 L.F. of channel.

2019-556 / Hunters Grove Road	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CCO / Channel - cleaned out	35.0	\$769.40	\$121.88	\$48.93	\$0.00	\$363.15	\$1,303.36
HAUL / Hauling	20.0	\$494.00	\$283.20	\$97.86	\$0.00	\$329.40	\$1,204.46
WSGRB / Workshelf - Grubbed	30.0	\$652.55	\$121.88	\$34.95	\$0.00	\$297.00	\$1,106.38
2019-556 / Hunters Grove Road Sub Total	86.0	\$1,937.74	\$526.96	\$181.74	\$0.00	\$989.55	\$3,635.99
Grand Total	86.0	\$1,937.74	\$526.96	\$181.74	\$0.00	\$989.55	\$3,635.99

(No Pictures Available)



Project: Hunters
Grove Road

Activity: Routine/
Preventive
Maintenance














Project #:
2019-556

Township/SW Dist:
St. Helena Island/8

Completed:
March 2019

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 25 50 100 150 200
Feet

1 inch = 100 feet

Prepared By: BC Stormwater Management Utility

Date Print: 04/12/19

File: C:\project summaries map\Hunters Grove Road_2019-556