

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Landing Hill Road

Activity: Routine/Preventive Maintenance

Duration: 11/08/18-11/28/18

Narrative Description of Project:

Replaced separated joint. Repaired washout.

2019-530 / Landing Hill Road	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CLPINP / Crossline Pipe - Inspected	20.0	\$431.58	\$18.00	\$0.00	\$0.00	\$214.65	\$664.22
CPRPL / Crossline Pipe - Replaced	15.0	\$302.05	\$75.26	\$63.46	\$0.00	\$127.20	\$567.97
HAUL / Hauling	16.0	\$338.38	\$226.56	\$515.82	\$0.00	\$144.20	\$1,224.96
RPWO / Repaired Washout	4.0	\$84.24	\$26.83	\$14.30	\$0.00	\$52.92	\$178.29
SD / Soft Digging	5.0	\$123.50	\$191.60	\$47.30	\$0.00	\$82.35	\$444.75
UTLOC / Utility locates	1.0	\$24.70	\$0.00	\$0.00	\$0.00	\$13.23	\$37.93
2019-530 / Landing Hill Road Sub Total	62.0	\$1,326.24	\$538.25	\$640.88	\$0.00	\$634.55	\$3,139.92
Grand Total	62.0	\$1,326.24	\$538.25	\$640.88	\$0.00	\$634.55	\$3,139.92
Before	During					After	

CAUTION CAUTION



(No Picture Available)



File:C:\project summaries map/Landing Hill Road_2019-530