



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Southern Magnolia Drive

Activity: Routine/Preventive Maintenance

Duration: 10/17/18-10/29/18

Narrative Description of Project:

Project improved 108 L.F. of drainage system. Cleaned out 108 L.F. of roadside ditch.

2018-615A / Southern Magnolia Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
HAUL / Hauling	8.0	\$178.16	\$113.28	\$75.48	\$0.00	\$115.36	\$482.28
RSDCL / Roadside Ditch - Cleanout	15.0	\$334.15	\$76.46	\$24.97	\$0.00	\$214.65	\$650.23
UTLOC / Utility locates	0.5	\$12.35	\$0.00	\$0.00	\$0.00	\$6.62	\$18.97
2018-615A / Southern Magnolia Drive Sub Total	24.5	\$546.45	\$189.74	\$100.45	\$0.00	\$336.62	\$1,173.27
Grand Total	24.5	\$546.45	\$189.74	\$100.45	\$0.00	\$336.62	\$1,173.27

(No Pictures Available)



Project: Southern Magnolia Drive

Activity: Routine/ Preventive Maintenance














Project #: 2018-615A

Township/SW Dist: Lady's Island/7

Completed: October 2018

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 120 feet

Prepared By: BC Stormwater Management Utility

Date Print: 05/20/19

File: C:\project summaries map\Southern Magnolia Drive_2018-615A