



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Wesley Avenue

Activity: Routine/Preventive Maintenance

Duration: 01/22/19-03/15/19

Narrative Description of Project:

Installed (1) driveway pipe.

2019-544 / Wesley Avenue	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
DPINS / Driveway Pipe - Installed	24.0	\$502.62	\$67.88	\$526.36	\$0.00	\$232.02	\$1,328.88
DWASPH / Driveway - Asphalt	20.0	\$431.58	\$87.18	\$33.44	\$0.00	\$214.65	\$766.85
HAUL / Hauling	12.5	\$296.60	\$177.00	\$904.22	\$0.00	\$195.63	\$1,573.45
2019-544 / Wesley Avenue Sub Total	57.5	\$1,252.59	\$332.06	\$1,464.02	\$0.00	\$642.29	\$3,690.96
Grand Total	57.5	\$1,252.59	\$332.06	\$1,464.02	\$0.00	\$642.29	\$3,690.96

Before



During



After





Project: Wesley Avenue

Activity: Routine/ Preventive Maintenance














Project #: 2019-544

Township/SW Dist: Port Royal Island/6

Completed: March 2019

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 42 feet