

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Mink Point Boulevard Channel #1

Activity: Routine/Preventive Maintenance

Duration: 07/16/18-08/16/18

Narrative Description of Project:

Project improved 2,008 L.F. of drainage system. Grubbed and cleared 314 L.F. of workshelf. Bush hogged 2,008 L.F of channel. Cleaned out 1,270 L.F. of channel.

2019-500 / Mink Point Boulevard Channel #1	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CBH / Channel- bushhogged	20.0	\$421.35	\$212.54	\$43.08	\$0.00	\$266.30	\$943.27
CCO / Channel - cleaned out	60.0	\$1,832.20	\$349.27	\$72.63	\$0.00	\$821.80	\$3,075.90
HAUL / Hauling	62.0	\$1,348.55	\$909.52	\$587.62	\$0.00	\$374.12	\$3,219.81
WGRSB / Workshelf- Grubbed	30.0	\$649.00	\$124.29	\$55.15	\$0.00	\$388.80	\$1,217.24
2019-500 / Mink Point Boulevard Channel #1 Sub Total	173.0	\$4,272.89	\$1,595.62	\$758.48	\$0.00	\$1,851.02	\$8,478.01
Grand Total	173.0	\$4,272.89	\$1,595.62	\$758.48	\$0.00	\$1,851.02	\$8,478.01

(No Pictures Available)



