

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Scott Hill Road Channel #2

Activity: Routine/Preventive Maintenance

Duration: 06/04/18-06/20/18

Narrative Description of Project:

Project improved 2,757 L.F. of drainage system. Bush hogged 1,047 L.F. of channel and 790 L.F. of roadside ditch. Cleaned out 1,440 L.F. of channel and 790 L.F. of roadside ditch.

2018-616 / Scott Hill Road Channel #2	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CCO / Channel - cleaned out	40.0	\$830.60	\$733.80	\$50.20	\$0.00	\$520.70	\$2,135.30
HAUL / Hauling	28.0	\$601.96	\$221.64	\$180.72	\$0.00	\$383.87	\$1,388.19
LM / Loading Materials	15.0	\$360.80	\$61.60	\$50.95	\$0.00	\$205.45	\$678.80
2018-616 / Scott Hill Road Channel #2 Sub Total	84.0	\$1,815.15	\$1,017.04	\$281.87	\$0.00	\$1,110.02	\$4,224.08
Grand Total	84.0	\$1,815.15	\$1,017.04	\$281.87	\$0.00	\$1,110.02	\$4,224.08

Before During After









