



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Tanglewood Drive

Activity: Routine/Preventive Maintenance

Duration: 10/02/18-10/15/18

Narrative Description of Project:

Project improved 155 L.F. of drainage system. Cleaned out 155 L.F. of channel.

2019-522 / Tanglewood Drive	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CCO / Channel - cleaned out	20.0	\$790.50	\$86.16	\$47.90	\$0.00	\$288.90	\$1,213.46
CLPINP / Crossline Pipe - Inspected	4.0	\$89.12	\$76.64	\$0.00	\$0.00	\$57.36	\$223.12
HAUL / Hauling	10.0	\$222.80	\$219.26	\$110.08	\$0.00	\$144.20	\$696.34
UTLOC / Utility locates	1.0	\$24.70	\$0.00	\$0.00	\$0.00	\$13.23	\$37.93
2019-522 / Tanglewood Drive Sub Total	36.0	\$1,148.91	\$382.06	\$157.98	\$0.00	\$503.69	\$2,192.64
Grand Total	36.0	\$1,148.91	\$382.06	\$157.98	\$0.00	\$503.69	\$2,192.64

(No Pictures Available)



Project:
Tanglewood Drive

Activity: Routine/
Preventive
Maintenance

Project #:
2019-522

Township/SW Dist:
Port Royal Island/6

Completed:
October 2018

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 30 60 120 180 240
Feet

1 inch = 130 feet

Prepared By: BC Stormwater Management Utility

Date Print: 02/13/19

File: C:\project summaries map\Tanglewood Drive 2019-522