



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Clydesdale Circle

**Activity:** Routine/Preventive Maintenance

**Duration:** 06/17/19-08/02/19

**Narrative Description of Project:**

Replaced (1) driveway pipe.

**2019-576 / Clydesdale Circle**

	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CCSRT / Concrete construction	0.0	\$0.00	\$0.00	\$0.00	\$460.90	\$0.00	\$460.90
DPRPL / Driveway Pipe - Replaced	61.0	\$1,270.09	\$108.52	\$663.56	\$0.00	\$591.36	\$2,633.53
HAUL / Hauling	10.0	\$229.90	\$141.60	\$55.34	\$0.00	\$144.20	\$571.04
PP / Project Preparation	24.0	\$529.50	\$41.23	\$43.17	\$0.00	\$178.20	\$792.10
2019-576 / Clydesdale Circle Sub Total	96.0	\$2,051.28	\$291.35	\$762.07	\$460.90	\$913.76	\$4,479.36
<b>Grand Total</b>	<b>96.0</b>	<b>\$2,051.28</b>	<b>\$291.35</b>	<b>\$762.07</b>	<b>\$460.90</b>	<b>\$913.76</b>	<b>\$4,479.36</b>

**Before**



**During**



**After**

**(No Pictures Available)**



Project: Clydesdale Circle

Activity: Routine/  
Preventive  
Maintenance

Project #:  
2019-576

Township/SW Dist:  
Port Royal Island/6

Completed:  
August 2019



Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 170 feet

Prepared By: BC Stormwater Management Utility  
Date Print: 09/24/19  
File: C:\project summaries map\Clydesdale Circle\_2019-576