



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Haynes Road

Activity: Routine/Preventive Maintenance

Duration: 07/08/19-07/17/19

Narrative Description of Project:

Replaced (1) crossline pipe.

2020-581 / Haynes Road

	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CPRPL / Crossline Pipe - Replaced	18.0	\$400.98	\$114.16	\$383.50	\$0.00	\$257.58	\$1,156.22
HAUL / Hauling	6.0	\$133.62	\$84.96	\$21.68	\$0.00	\$86.52	\$326.78
UTLOC / Utility locates	0.5	\$10.90	\$0.00	\$0.00	\$0.00	\$0.00	\$10.90
2020-581 / Haynes Road Sub Total	25.5	\$567.29	\$199.12	\$405.18	\$0.00	\$344.10	\$1,515.69
Grand Total	25.5	\$567.29	\$199.12	\$405.18	\$0.00	\$344.10	\$1,515.69

Before




During



After





Project: Haynes Road

Activity: Routine/
Preventive
Maintenance














Project #:
2020-581

Township/SW Dist:
Sheldon/5

Completed:
July 2019

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 83 feet