

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Scott Hill Road Channel #1

Activity: Routine/Preventive Maintenance

Duration: 07/17/19-07/23/19

Narrative Description of Project:

Project improved 3,099 L.F. of drainage system. Cleaned out 1,482 L.F. of channel and 1,617 L.F. of roadside ditch.

2020-002 / Scott Hill Road Channel #1	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CCO / Channel - cleaned out	80.0	\$2,160.30	\$908.38	\$191.83	\$0.00	\$830.40	\$4,090.91
HAUL / Hauling	34.0	\$760.06	\$481.44	\$196.56	\$0.00	\$432.60	\$1,870.66
2020-002 / Scott Hill Road Channel #1 Sub Total	115.0	\$2,942.15	\$1,389.82	\$388.39	\$0.00	\$1,263.00	\$5,983.36
Grand Total	115.0	\$2,942.15	\$1,389.82	\$388.39	\$0.00	\$1,263.00	\$5,983.36

(No Pictures Available)



