

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Port Royal Island Washout/Sinkhole Repair

Blue Dolphin Drive, Mint Farm Drive, Godwin Road, Bostick Circle,

Bostick Road

Narrative Description of Project:

Repaired sinkholes and washouts. Installed rip rap for erosion control.

Activity: Routine/Preventive Maintenance

Duration: 02/20/19-06/27/19

2019-317A / Port Royal Island Washout/Sinkhole Repair	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	2.0	\$43.58	\$0.00	\$0.00	\$0.00	\$0.00	\$43.58
HAUL / Hauling	33.0	\$736.43	\$467.28	\$633.80	\$0.00	\$327.49	\$2,165.00
RPWO / Repaired Washout	38.0	\$810.16	\$130.53	\$111.95	\$0.00	\$436.68	\$1,489.32
SD / Soft Digging	20.0	\$443.38	\$383.20	\$89.09	\$0.00	\$213.54	\$1,129.21
SR / Sinkhole repair	117.0	\$2,648.57	\$574.50	\$1,004.83	\$0.00	\$1,209.33	\$5,437.23
2019-317A / Port Royal Island Washout/Sinkhole Repair Sub Total	210.0	\$4,682.12	\$1,555.51	\$1,839.67	\$0.00	\$2,187.04	\$10,264.34
Grand Total	210.0	\$4,682.12	\$1,555.51	\$1,839.67	\$0.00	\$2,187.04	\$10,264.34

Before





During





After













Project: Port Royal Island Washout / Sinkhole Repair -**Bostick Circle** Map #5

Activity: Routine/ Preventive Maintenance

Project #: 2019-317A

Township/SW Dist: Port Royal Island/

Completed: June 2019

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
 - Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

File:C:\project summaries map/PRI Washout Repair- Bostick Circle Map #5_2019-317A