

Beaufort County Public Works Stormwater Infrastructure

Project Summary

Project Summary: Franklin Drive

Activity: Routine/Preventive Maintenance **Duration:** 09/24/19-09/30/19

Narrative Description of Project:

Project improved 3,560 L.F. of drainage system. Bush hogged 1,669 L.F. and cleaned out 2,381 L.F. of channel.

2020-012 / Franklin Drive	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CBH / Channel- bushhogged	30.0	\$608.25	\$322.92	\$68.67	\$0.00	\$198.45	\$1,198.29
CCO / Channel - cleaned out	114.0	\$2,598.24	\$539.84	\$131.76	\$0.00	\$1,349.46	\$4,619.30
HAUL / Hauling	38.0	\$869.30	\$538.08	\$551.48	\$0.00	\$86.52	\$2,045.38
2020-012 / Franklin Drive Sub Total	183.0	\$4,097.58	\$1,400.84	\$751.91	\$0.00	\$1,634.43	\$7,884.76
Grand Total	183.0	\$4,097.58	\$1,400.84	\$751.91	\$0.00	\$1,634.43	\$7,884.76

Before


During

After



(No Picture Available)







480 0 60 120 240 360 Feet

1 inch = 250 feet

Date Print:10/10/19 File:C:\project summaries map/Franklin Drive Map #1_2020-012



File:C:\project summaries map/Franklin Drive Map #2_2020-012



File:C:\project summaries map/Franklin Drive Map #3_2020-012