



**Beaufort County Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Bluffton Parkway

**Activity:** Routine/Preventive Maintenance

**Duration:** 03/05/20-04/20/20

**Narrative Description of Project:**

Dewatered road. Cleaned out (2) catch basins. Jetted (1) crossline pipe.

<b>2020-035 / Bluffton Parkway</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CLPJT / Crossline Pipe - Jetted	20.0	\$441.90	\$383.20	\$95.49	\$0.00	\$164.70	\$1,085.29
DWR / Dewatered Road	105.0	\$2,285.85	\$806.60	\$175.88	\$0.00	\$802.80	\$4,071.12
2020-035 / Bluffton Parkway Sub Total	126.0	\$2,749.54	\$1,189.80	\$271.37	\$0.00	\$967.50	\$5,178.20
<b>Grand Total</b>	<b>126.0</b>	<b>\$2,749.54</b>	<b>\$1,189.80</b>	<b>\$271.37</b>	<b>\$0.00</b>	<b>\$967.50</b>	<b>\$5,178.20</b>

**(No Pictures Available)**



Project: Bluffton Parkway

Activity: Routine/ Preventive Maintenance














Project #: 2020-035

Township/SW Dist: Bluffton/4

Completed: April 2020

**Legend**

**Drainage Type**

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 250 feet

Prepared By: BC Stormwater Management Utility  
 Date Print: 09/17/20  
 File: C:\project summaries map\Bluffton Parkway\_2020-035