



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Bluffton Sinkhole Repair - Wentworth Drive

Activity: Routine/Preventive Maintenance

Duration: 02/04/20-06/10/20

Narrative Description of Project:

Repaired (2) sinkholes.

2020-319 / Bluffton Sinkhole Repair	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CBIN / Catch basin - inspected	6.0	\$132.57	\$114.96	\$13.21	\$0.00	\$49.41	\$310.15
HAUL / Hauling	10.0	\$226.30	\$141.60	\$45.35	\$0.00	\$72.10	\$485.35
SR / Sinkhole repair	87.0	\$1,818.43	\$472.67	\$220.89	\$0.00	\$657.24	\$3,169.22
2020-319 / Bluffton Sinkhole Repair Sub Total	104.0	\$2,199.09	\$729.23	\$279.44	\$0.00	\$778.75	\$3,986.51
Grand Total	104.0	\$2,199.09	\$729.23	\$279.44	\$0.00	\$778.75	\$3,986.51

(No Picture Available)



Project: Bluffton Washout Repair-
Wentworth Drive

Activity: Routine/
Routine Preventive/
Maintenance














Project #:
2020-319

Township/SW Dist:
Bluffton/4

Completed:
June 2020

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 83 feet

Prepared By: BC Stormwater Management Utility

Date Print:09/17/20

File:C:\project summaries map\Bluffton Washout Repair- Wentworth Drive_2020-038