

## Beaufort County Public Works Stormwater Infrastructure

**Project Summary** 

Project Summary: Chisholm Hill Road Channel #1

**Activity:** Routine/Preventive Maintenance

**Duration:** 12/14/20-12/17/20

## **Narrative Description of Project:**

Project improved 3,750 L.F. of drainage system. Cleaned out 3,750 L.F. of channel.

2021-524 / Chisholm Hill Road Channel #1	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
CCO / Channel - cleaned out	64.0	\$1,336.56	\$402.12	\$76.72	\$0.00	\$504.72	\$2,320.12
HAUL / Hauling	33.0	\$702.11	\$433.66	\$102.00	\$0.00	\$333.30	\$1,571.07
2021-524 / Chisholm Hill Road Channel #1 Project Sub Total	98.0	\$2,060.46	\$835.78	\$178.72	\$0.00	\$838.02	\$3,912.98
Grand Total	98.0	\$2,060.46	\$835.78	\$178.72	\$0.00	\$838.02	\$3,912.98

(Before ) (During) (After )







