



Beaufort County Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Lady's Island Valley Drains - Varsity Street

Activity: Routine/Preventive Maintenance

Duration: 12/11/19-12/13/19

Narrative Description of Project:

Project improved 200 L.F. of drainage system. Cleaned 200 L.F. of valley drains and installed #57 stone for erosion control. This project consisted of the following area: Varsity Street (200 L.F.)

2020-313 / Lady's Island Valley Drains	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	1.0	\$21.79	\$0.00	\$0.00	\$0.00	\$0.00	\$21.79
COVD / Cleaned Out Valley Drains	14.0	\$317.45	\$90.83	\$33.67	\$0.00	\$148.50	\$590.44
HAUL / Hauling	5.0	\$114.95	\$70.80	\$304.76	\$0.00	\$0.00	\$490.51
2020-313 / Lady's Island Valley Drains Project Sub Total	20.0	\$454.19	\$161.63	\$338.43	\$0.00	\$148.50	\$1,102.74
Grand Total	20.0	\$454.19	\$161.63	\$338.43	\$0.00	\$148.50	\$1,102.74

(No Pictures Available)



Project: Lady's
Island Valley
Drains - Varsity
Street

Activity: Routine/
Preventive
Maintenance














Project #:
2020-313

Township/SW Dist:
Lady's Island/7

Completed:
December 2019

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 25 50 100 150 200
Feet

1 inch = 100 feet

Prepared By: BC Stormwater Management Utility

Date Print: 11/23/20

File: C:\project summaries map\Lady's Island Valley Drains - Varsity Street_2020-313