

Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Peaches Hill Circle Channel

Activity: Routine/Preventive Maintenance **Duration**: 12/14/20 - 01/16/21

Narrative Description of Project:

This project improved 7,250 L.F. of drainage system. Cleaned out 446 L.F. of roadside ditch and 6,804 L.F. of channel.

2021-522 / Peaches Hill Circle Channel	Labor	Labor	Equipment	Material	Contractor	Indirect	Total
	Hours	Cost	Cost	Cost	Cost	Labor	Cost
AUDIT / Audit Project	1.5	\$32.69	\$0.00	\$0.00	\$0.00	\$0.00	\$32.69
CCO / Channel - cleaned out	247.0	\$5,074.74	\$2,036.15	\$339.36	\$0.00	\$1,989.93	\$9,440.18
HAUL / Hauling	74.0	\$1,681.13	\$1,353.26	\$223.01	\$0.00	\$403.76	\$3,661.16
RSDCL / Roadside Ditch - Cleanout	32.0	\$651.76	\$119.76	\$27.00	\$0.00	\$309.36	\$1,107.88
2021/522 Peaches Hill Circle Channel Project Sub Total	354.5	\$7,440.32	\$3,509.17	\$589.37	\$0.00	\$2,703.05	\$14,241.90
Grand Total	354.5	\$7,440.32	\$3,509.17	\$589.37	\$0.00	\$2,703.05	\$14,241.90

(Before)






(During)

(Ending)

(No Picture Available)





1 inch = 420 feet

Date Print:02/16/21 File:C:\project summaries map/Peaches Hill Circle and Scott Hill Road Channel #1 Map #2_2021-522