



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Riley Road Outfall

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 441 L.F. of drainage system. Cleaned out 441 L.F. of outfall ditch.

Completion: Feb-13

| 2013-602 / Riley Road Outfall | Labor Hours | Labor Cost | Equipment Cost | Material Cost | Contractor Cost | Indirect Labor | Total Cost |
|--|-------------|-------------------|-----------------|----------------|-----------------|-----------------|-------------------|
| AUDIT / Audit Project | 0.5 | \$10.45 | \$0.00 | \$0.00 | \$0.00 | \$6.62 | \$17.06 |
| HAUL / Hauling | 10.0 | \$218.50 | \$107.00 | \$37.95 | \$0.00 | \$144.20 | \$507.65 |
| ODCO / Outfall ditch - cleaned out | 30.0 | \$666.90 | \$105.76 | \$36.51 | \$0.00 | \$321.20 | \$1,130.37 |
| ONJV / Onsite Job Visit | 5.0 | \$153.97 | \$20.10 | \$17.70 | \$0.00 | \$119.36 | \$311.13 |
| 2013-602 / Riley Road Outfall Sub Total | 45.5 | \$1,049.82 | \$232.86 | \$92.16 | \$0.00 | \$591.38 | \$1,966.21 |
| | | | | | | | |
| Grand Total | 45.5 | \$1,049.82 | \$232.86 | \$92.16 | \$0.00 | \$591.38 | \$1,966.21 |

Before



During



After



Project: Riley Road

**Activity: Routine/
Preventive
Maintenance**
















**Project #:
2013-602**


**Township: Town
of Port Royal**

**Completed:
February 2013**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



1 inch = 111 feet

Prepared By: BC Stormwater Management Utility
Date Print: 3/18/13
File:C:/sethdata/projects/projectmaps/Riley Rd 2013-602