



Beaufort County Public Works Stormwater Infrastructure Project Summary

Project Summary: Southern Magnolia Drive - Rework

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Repaired washout.

Completion: Feb-13

2013-517R / Southern Magnolia Court	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	3.0	\$65.55	\$32.10	\$15.65	\$0.00	\$43.26	\$156.56
RPWO / Repaired Washout	12.0	\$275.04	\$24.12	\$58.40	\$0.00	\$176.37	\$533.93
2013-517R / Southern Magnolia Court Sub Total	15.5	\$351.04	\$56.22	\$74.05	\$0.00	\$226.25	\$707.55
Grand Total	15.5	\$351.04	\$56.22	\$74.05	\$0.00	\$226.25	\$707.55

Before



During



After



**Project: Southern
Magnolia Drive
Rework**

**Activity: Routine/
Preventive
Maintenance**
















**Project #:
2013-517R**

**Township: Lady's
Island**

**Completed:
February 2013**

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



1 inch = 43 feet