



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: St Helena Island Tree Removal - David Green Road Outfall

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Removed fallen tree from workshelf.

Completion: Nov-12

2013-575 / St Helena Island Tree Removal	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$10.45	\$0.00	\$0.00	\$0.00	\$6.62	\$17.06
HAUL / Hauling	2.0	\$43.70	\$21.40	\$24.57	\$0.00	\$28.84	\$118.51
RMTRW / Remove trees - Workshelf	6.0	\$141.16	\$47.44	\$12.80	\$0.00	\$89.80	\$291.20
2013-575 / St Helena Island Tree Removal Sub Total	8.5	\$195.31	\$68.84	\$37.37	\$0.00	\$125.26	\$426.77
Grand Total	8.5	\$195.31	\$68.84	\$37.37	\$0.00	\$125.26	\$426.77

(Pictures Not Available)

Project: David Green Road Outfall

Activity: Routine/ Preventive Maintenance
















Project #: 2013-575

Township: St. Helena Island

Completed: Novermeber 2012

Legend

TYPE

-  River
-  Creek/Stream
-  River/Creek/Marsh BANK
-  Channel (fka Outfall)
-  Channel Pipe
-  Lateral
-  Lateral Pipe
-  Roadside
-  Roadside Pipe
-  Road Pipe
-  Crossline Pipe
-  Driveway Pipe
-  Access Pipe
-  Bleeder Pipe
-  Parcels



Removed fallen tree from workshelf.



1 inch = 94 feet