

Project: Cee Cee Road

Activity: Routine/
Preventive
Maintenance

Project #:
2016-568A

Township/SW Dist:
St. Helena Island /8

Completed:
March 2016
















Cleaned out 1,062 LF
of roadside ditch.

Jetted (2) driveway pipes and
(2) crossline pipes.

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 250 feet