



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Gillison Loop Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 250 L.F. of drainage system. Cleaned out 250 L.F. of channel.

Duration: 4/11/16

2016-616 / Gillison Loop Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
CCO / Channel - cleaned out	30.0	\$641.20	\$96.22	\$10.30	\$0.00	\$408.00	\$1,155.72
HAUL / Hauling	5.0	\$111.35	\$39.95	\$15.86	\$0.00	\$72.10	\$239.26
2016-616 / Gillison Loop Channel #1 Sub Total	35.5	\$764.30	\$136.17	\$26.16	\$0.00	\$486.71	\$1,413.33
Grand Total	35.5	\$764.30	\$136.17	\$26.16	\$0.00	\$486.71	\$1,413.33

Before



During



After



Project: Gillison Loop Channel #1

Activity: Routine/
Preventive
Maintenance














Project #:
2016-616

Township/SW Dist:
Port Royal Island/7

Completed:
April 2016

Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



0 20 40 80 120 160
Feet

1 inch = 83 feet

Prepared By: BC Stormwater Management Utility
Date Print: 05/12/16
File: C:\project summaries map\Gillison Loop_2016-616