



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Big Estate Circle Channel #1

Activity: Routine/Preventive Maintenance

Narrative Description of Project:

Project improved 1,750 L.F. of drainage system. Cleaned out 1,750 L.F. of channel.

Completion: Jan-16

2016-576 / Big Estate Circle Channel #1	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Cost	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
CCO / Channel - cleaned out	102.0	\$2,406.02	\$623.08	\$62.75	\$0.00	\$1,530.14	\$4,621.99
ONJV / Onsite Job Visit	6.0	\$214.20	\$21.40	\$12.16	\$0.00	\$140.84	\$388.60
2016-576 / Big Estate Circle Channel #1 Sub Total	108.5	\$2,631.97	\$644.48	\$74.91	\$0.00	\$1,677.60	\$5,028.95
Grand Total	108.5	\$2,631.97	\$644.48	\$74.91	\$0.00	\$1,677.60	\$5,028.95

Before



During



After



Project: Big Estate Circle Channel #1

Activity: Routine/
Preventive
Maintenance

Project #:
2016-576














Township/SW Dist:
Sheldon/5

Completed:
January 2016



Legend

Drainage Type

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe

0 50 100 200 300 400
Feet

1 inch = 210 feet

Prepared By: BC Stormwater Management Utility

Date Print:01/11/16

File:C:\project summaries map\Big Estate Circle Channel #1_2016-576