



Beaufort County
Public Works
Stormwater Infrastructure
Project Summary

Project Summary: Port Royal Island Valley Drains

Activity: Routine/Preventive Maintenance


Narrative Description of Project:

Duration: 7/5/16 - 7/12/16

Project improved 1,490 L.F. of drainage system. Cleaned out 1,490 L.F. of valley drains. This project consisted of the following area: Smalls Hill Road (1,490 L.F.).

2017-314 / Port Royal Island Valley Drains	Labor Hours	Labor Cost	Equipment Cost	Material Cost	Contractor Cost	Indirect Labor	Total Cost
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
COVD / Cleaned Out Valley Drains	13.0	\$280.92	\$60.40	\$16.74	\$0.00	\$173.79	\$531.85
2017-314 / Port Royal Island Valley Drains	13.5	\$292.67	\$60.40	\$16.74	\$0.00	\$180.41	\$550.21
Sub Total							
Grand Total	13.5	\$292.67	\$60.40	\$16.74	\$0.00	\$180.41	\$550.21

(Pictures Not Available)



Project: Port Royal
Island Valley
Drains - Smalls Hill
Road

Activity: Routine/
Preventive
Maintenance

Project #:
2017-314

Township/SW Dist:
Port Royal Island/6

Completed:
July 2016

Legend

Drainage Type

- Access Pipe
- Bleeder Pipe
- Channel Pipe
- Channel
- Stream
- Crossline Pipe
- Driveway Pipe
- Lateral
- Lateral Pipe
- River
- Road Pipe
- Roadside
- Roadside Pipe

0 30 60 120 180 240
Feet

1 inch = 130 feet

Prepared By: BC Stormwater Management Utility

Date Print: 01/26/17

File: C:\project summaries map\Port Royal Island Valley Drains- Smalls Hill Road_2017-314