



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Sheridan Park Circle - Pennington Drive

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Project improved 2,330 L.F. of drainage system. Cleaned out 2,330 L.F. of roadside ditch. Jetted (1) crossline pipe and (11) driveway pipes.

**Duration:** 6/14/16 - 8/19/17

<b>2016-623 / Sheridan Park Circle-Pennington Dr</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
DLO / Ditch Layout	30.0	\$697.50	\$35.40	\$18.18	\$0.00	\$431.40	\$1,182.48
DPJT / Driveway Pipe - Jetted	20.0	\$463.70	\$86.80	\$97.09	\$0.00	\$297.85	\$945.44
HAUL / Hauling	113.0	\$2,632.18	\$1,010.12	\$495.05	\$0.00	\$1,726.64	\$5,863.99
ONJV / Onsite Job Visit	6.0	\$205.08	\$21.24	\$16.00	\$0.00	\$146.82	\$389.14
PP / Project Preparation	49.0	\$1,096.59	\$72.00	\$26.61	\$0.00	\$681.63	\$1,876.83
RSDCL / Roadside Ditch - Cleanout	318.0	\$7,164.06	\$1,097.46	\$242.20	\$0.00	\$4,401.49	\$12,905.21
<b>2016-623 / Sheridan Park Circle-Pennington Dr Sub Total</b>	<b>536.5</b>	<b>\$12,270.85</b>	<b>\$2,323.02</b>	<b>\$895.13</b>	<b>\$0.00</b>	<b>\$7,692.44</b>	<b>\$23,181.44</b>
<b>Grand Total</b>	<b>536.5</b>	<b>\$12,270.85</b>	<b>\$2,323.02</b>	<b>\$895.13</b>	<b>\$0.00</b>	<b>\$7,692.44</b>	<b>\$23,181.44</b>

Before



After



Project: Sheridan Park Circle - Pennington Drive Map #1

Activity: Routine/ Preventive Maintenance

Project #: 2016-623

Township/SW Dist: Bluffton/4

Completed: August 2017




Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 170 feet





Project: Sheridan Park Circle - Pennington Drive Map #2

Activity: Routine/ Preventive Maintenance

Project #: 2016-623

Township/SW Dist: Bluffton/4

Completed: August 2017

Legend	
<b>Drainage Type</b>	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 170 feet

Prepared By: BC Stormwater Management Utility  
Date Print: 03/02/17

File: C:\project summaries map\Sheridan Park Circle - Pennington Drive Map #2\_2016-623