



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Camp St Marys Road Debris Removal

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Removed debris.

**Duration:** 8/17/17 - 8/28/17

<b>2018-520 / Camp St Marys Rd</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
DEBRIS / Debris Removal	75.0	\$1,701.00	\$508.25	\$115.91	\$0.00	\$935.45	\$3,260.61
HAUL / Hauling	32.0	\$729.65	\$301.44	\$481.03	\$0.00	\$475.79	\$1,987.91
<b>2018-520 / Camp St Marys Rd Sub Total</b>	<b>107.5</b>	<b>\$2,442.40</b>	<b>\$809.69</b>	<b>\$596.94</b>	<b>\$0.00</b>	<b>\$1,417.85</b>	<b>\$5,266.88</b>
<b>Grand Total</b>	<b>107.5</b>	<b>\$2,442.40</b>	<b>\$809.69</b>	<b>\$596.94</b>	<b>\$0.00</b>	<b>\$1,417.85</b>	<b>\$5,266.88</b>

During



After





Project: Camp St Marys Road

Activity: Routine/ Preventive Maintenance














Project #: 2018-520

Township/SW Dist: Bluffton/4

Completed: July 2017

**Legend**

**Drainage Type**

-  Access Pipe
-  Bleeder Pipe
-  Channel Pipe
-  Channel
-  Stream
-  Crossline Pipe
-  Driveway Pipe
-  Lateral
-  Lateral Pipe
-  River
-  Road Pipe
-  Roadside
-  Roadside Pipe



1 inch = 210 feet