



**Beaufort County**  
**Public Works**  
**Stormwater Infrastructure**  
*Project Summary*

**Project Summary:** Sheldon Tree Removal - Huspah Court South

**Activity:** Routine/Preventive Maintenance

**Narrative Description of Project:**

Removed fallen trees from flowline.

**Duration:** 9/16/17

<b>2017-319 / Sheldon Tree Removal</b>	<b>Labor Hours</b>	<b>Labor Cost</b>	<b>Equipment Cost</b>	<b>Material Cost</b>	<b>Contractor Cost</b>	<b>Indirect Labor</b>	<b>Total Cost</b>
AUDIT / Audit Project	0.5	\$11.75	\$0.00	\$0.00	\$0.00	\$6.62	\$18.36
RMTRD / Remove trees - Ditch	20.0	\$466.04	\$91.25	\$24.76	\$0.00	\$304.96	\$887.01
<b>2017-319 / Sheldon Tree Removal Sub Total</b>	<b>20.5</b>	<b>\$477.79</b>	<b>\$91.25</b>	<b>\$24.76</b>	<b>\$0.00</b>	<b>\$311.58</b>	<b>\$905.37</b>
<b>Grand Total</b>	<b>20.5</b>	<b>\$477.79</b>	<b>\$91.25</b>	<b>\$24.76</b>	<b>\$0.00</b>	<b>\$311.58</b>	<b>\$905.37</b>

(Pictures Not Available)



Project: Sheldon Tree Removal-Huspah Court South

Activity: Routine/Preventive Maintenance

Project #: 2017-319

Township/SW Dist: Sheldon/5

Completed: September 2017

Legend	
Drainage Type	
	Access Pipe
	Bleeder Pipe
	Channel Pipe
	Channel
	Stream
	Crossline Pipe
	Driveway Pipe
	Lateral
	Lateral Pipe
	River
	Road Pipe
	Roadside
	Roadside Pipe



1 inch = 200 feet

Prepared By: BC Stormwater Management Utility

Date Print: 02/05/18

File: C:\project summaries map\Sheldon Tree Removal-Huspah Court South\_2017-319